

## INVESTIGATION REPORT Building and Safety/Land Development Division

Location of Problem: 1113 E. 8547 St.
Locality:
Description of Problem: Sewage being exected
Aron private residence into
Alley
Requested by: Les Novman, Kand Lept
Request call back after investigation? Yes No No
deceived by:
ssigned/Referred to: Seval Co
eport of Investigation:
vestigator: Date: Date:
ppy Sent to: Date: Date:
port Phoned to: Title: Date:
DISKFORMS/INVEST.RPT

JOB ADDRESS	1113	E. 85 ST
OWNER	1115	A DUPLEX

## NOTICE OF VIOLATION

The work performed is in viola indicated below:	tion of the Ordinance(s)	
Building Code	L Flumbing Code	
Mechanical Code	Electrical Code	
Grading Code	Zoning Code	
DESCRIPTION: RAV	YWATER SEWAGE	
LOTAKIACO.	From	
A Muni	31NG	
DRAM LI	NE DU	
THE WES	TSIDE	
OF THE	HOUSE	
RIGHT OF	PUBLIC DA Allay	
TOPPECENT	FURTHER	
STOP ALL V	VORK -	
Submit plans for the cited work within 10 days to the office listed above and apply for a plan check for the required permit(s).  REPAIR LEAK WITHIN TWO DAYS Obtain permit(s) within 10 days at the office listed above for the cited work.		
Section of the Dep Planning, L.A.	n made to the Enforcement artment of Regional COUNTY	
3-23-200 /	Pulariz	
DATE	INSPECTOR'S SIGNATURE	